



Storage and Care of wires

Storage and Care of Stainless, Nickel-Alloy steel Wires and Rods

To maintain the as-delivered clean content as long as possible the handling and the storage of the wire must be done according to the following recommendations.

Transport

Transportation of the wire must be done in covered vehicles.

Packages must be in dry cardboard boxes with plastic bags inside or in sealed drums on undamaged pallets.

Unprotected containers and wire packages must not be exposed to direct wetness, like snow and rain.

Damaged containers must be repacked within one hour, otherwise they should be scrapped.

Storage

Common rule for stock is first-in, first-out / separating wire lot-no.

Unopened wire boxes or drums must be kept under properly maintained and controlled storage conditions as follows:

- Temperature Should be between 5°C and 50°C
- Relative Humidity As low as possible, not exceeding 80%

When handled and stored as mentioned above, the wires can normally be used as long as they are surface without defect.